



ALPHA GAP AR 111

HALÓGENO - LOW VOLTAGE

ALPHA GAP IV




	CLAVE A	CLAVE B	VOLTAJE DE ALIMENTACIÓN
■	02-G07-331	L-1690-0	127V~± 10%
■	02-G07-332	L-1690-1	127V~± 10%
■	02-G07-333	L-1690-2	127V~± 10%



ALPHA GAP II




	CLAVE A	CLAVE B	VOLTAJE DE ALIMENTACIÓN
■	02-G05-331	L-1688-0	127V~± 10%
■	02-G05-332	L-1688-1	127V~± 10%
■	02-G05-333	L-1688-2	127V~± 10%



ALPHA GAP III




	CLAVE A	CLAVE B	VOLTAJE DE ALIMENTACIÓN
■	02-G06-331	L-1689-0	127V~± 10%
■	02-G06-332	L-1689-1	127V~± 10%
■	02-G06-333	L-1689-2	127V~± 10%



ALPHA AR 111: ROUND, A RIEL Y A CÁNOPE

HALÓGENO - LOW VOLTAGE


ALPHA ROUND



	CLAVE A	CLAVE B	VOLTAJE DE ALIMENTACIÓN
■	02-G15-331	L-1853-0	127V~± 10%
■	02-G15-332	L-1853-1	127V~± 10%
■	02-G15-333	L-1853-2	127V~± 10%

Incluir
 AR111 Includida 12V
 1/50W
 3000
 10
 165 mm
 Empotrar

ALPHA A RIEL




	CLAVE A	CLAVE B	VOLTAJE DE ALIMENTACIÓN
■	02-909-331	K-1659-0	127V~± 10%
■	02-909-332	K-1659-1	127V~± 10%
■	02-909-333	K-1659-2	127V~± 10%

Incluir
 AR111 Includida 12V
 50W
 3000
 10
 Sobreponer



ALPHA A CÁNOPE



	CLAVE A	CLAVE B	VOLTAJE DE ALIMENTACIÓN
■	02-609-331	K-1671-0	127V~± 10%
■	02-609-332	K-1671-1	127V~± 10%
■	02-609-333	K-1671-2	127V~± 10%

Incluir
 AR111 Includida 12V
 50W
 3000
 10
 Sobreponer